

Vehicle Diagnostic Report

The Report is created by **LAUNCH X431**

Repair Shop

Shop Name:
Address:
Zip Code:
Telephone:
Email:
SN:985496008893
Test Time:2021-07-12 10:58:37



Vehicle Information

Year:2012
Make:GM
Model:Ampera
VIN:1G0R86E47CU121424
Engine Size:LUU - FFV, E-Flex, FAM 1.4
Vehicle Software Version:V48.50
Diagnostic Application Version:V5.00.014
Diagnostic path:Manually Select (Via Model) > Chevrolet > (C) 2012 > Volt > System Selection > Hybrid Powertrain Control Module 2 (HPCM2)



Inspection Result

Hybrid Powertrain Control Module 2 (HPCM2) 1 problem exist

1.P1FFF-00 System Isolation / Coolant Level Sensor Fault - Hybrid/EV Battery Charging System Disabled

Current
This Ignition Cycle: Passed And Failed
Last Test: Failed Current DTC
Since DTC Clear: Passed And Failed
DTC History Status: History
Malfunction Indicator Lamp (MIL) Status: Requested